




# NAVAL AIR STATION FORT WORTH JRB CARSWELL FIELD TEXAS

### ADMINISTRATIVE RECORD COVER SHEET

AR File Number <u>583</u>

Barry R McBee, Chairman R B "Ralph" Marquez, Commissioner John M Baker, Commissioner Jeffrey A Saitas, Executive Director





JAN 0 4 REC'D

- - vice 5

#### TEXAS NATURAL RESOURCE CONSERVATION COMMISSION

Protecting Texas by Reducing and Preventing Pollution

December 29, 1998

CERTIFIED MAIL - Z 435653165

MR. OLEN LONG US AIR FORCE - AFBCA - DC CARSWELL 3711 OUTLAW COUNTRY DR AUSTIN, TX 78719 2800

Re: Subsurface release at the CARSWELL AFB facility located at BLDG 1170, FORT WORTH

(Tarrant County), Texas

(LPST ID No. 104819 PST Facility No.0009696)

Dear Mr. Olen Long:

This letter is to inform you that your response documenting the next phase of corrective action for the above-referenced Leaking Petroleum Storage Tank (LPST) site has not been received by the Texas Natural Resource Conservation Commission (TNRCC). We request that you contact an environmental consultant who is registered as a Corrective Action Specialist (CAS) to review the information available on your site and recommend the next appropriate phase of corrective action. Please note that the TNRCC requires written approval for all corrective action activities prior to initiation in order for reimbursement claims for those activities to be processed in the order received. If you are seeking reimbursement, a workplan and cost proposal must be submitted for review and preapproval prior to initiation of any activity. If you have submitted a proposal, a report, or a site closure request within the past 14 days, please disregard this letter.

At this time you are requested to express your intentions to address the above-referenced incident. Your response must be submitted to this Office no later than 30 days from the date of this letter. Your failure to respond within the requested time frame is a violation of Title 30 TAC Chapter 334. Further delays in responding to this Office will result in the initiation of formal enforcement actions against you. The LPST and Facility ID Numbers should be included on all correspondence.

Should you have any questions, please contact the PST Responsible Party Remediation Section at 512/239-5055. Your prompt attention to this matter will be appreciated.

Sincerely,

Alan R. Batcheller, Manager

alan R. Bothle

PST Responsible Party Remediation Section

Remediation Division

104819.lnp

# FINAL PAGE

## **ADMINISTRATIVE RECORD**

FINAL PAGE